AUTOMOTIVE SUNROOF & TRIMMING SERVICES

43 REGENT ST, OAKLEIGH VIC 3166, AUSTRALIA ABN: 45.007.202.833

EMAIL: asrts@bigpond.com

PHONE: 03 9568 0015

FAX: 03 9568 0079

INSPECTION REPORT 5617

INSPECTION REPORT

Date: 24/01/2014

Customer-

B& A MOTOR BODY REPAIRS

Name: Address:

1848 Princes H'way

CLAYTON

VIC 3168

Code:

BA01

Contact:

DOM

Phone: Fax:

9543 7777 9562 8760

Mobile:

Order No:

XVE027

XVF027

Registration No Make:

HYUNDAI

Model:

Month/Year:

01/2010

INV REF Report Type:

INSR

Eng. No: VIN:

G4KJAH004533

KMHFC41DMBA160352

Authorised

Vehicle kms

24/01/2014

Date Required: Checked by:

PHILIP NEAL

Our senior sunroof specialist has inspected the vehicle and the damage to the sunroof on behalf of B&A Motor Body Repairs. It is our professional opinion that the damage sustained to the sunroof is consistent with a foreign body impact.

Our senior sunroof specialist has been able to identify evidence of stone chip damage located on both the grill and windscreen of this vehicle. We have images available that identifies this damage.

It is our professional opinion that a stone or foreign object has struck the vehicle. Damage has been sustained to the vehicle and the foreign body/stone been reflected to the sunroof glass panel causing it to break.

The sunroof glass panel is manufactured in toughened glass which is designed to shatter on impact.

With over thirty years experience in the sunroof industry, our technicans are highly experienced in dealing with and assessing vehicles that sustain damage to sunroofs. Our workshop technicians assess many vehicles annually that have sustained similar damage.

Our general operating procedure when inspecting a vehicle which has sustained damage to the sunroof is to assess the vehicle and advise the customer of their options for repairing their vehicle.

If the client has motor vehicle insurance policy that covers damage to sunroofs, we would generally recommend that a claim is lodged with their insurance company.

> Once a claim is lodged, our office is then able to prepare a quote that will cover the repair to the vehicle. It is possible that the quote would contain prices to replace both the sunroof glass panel and the sunroof mechanism complete.

Upon request we will prepare a quote to repair the damage to the sunroof which includes both the labour involved in the repair and the parts required.

Philip Neal Director